

Date: Monday, 05/11/2007 11:22:05 AM
User: Linda Lacelle

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services
Job Number : 33632
Estimate Number : 10467
P.O. Number :
This Issue : 05/11/2007 **S.O. No.** :
Prsht Rev. : NC
First Issue : 19/07/2007 **Type** : MACHINED PARTS
Previous Run : 33631
Written By :
Checked & Approved By :
Comment : Est. A 05.09.13 New issue KJ/JLM
Est. B 06.02.10 Dwg rev.D ech 773 EC
Est. C 06.05.02 Added inspections EC
est D 07.03.13 rev F dwg EC

Drawing Name : FWD TUBE ASSEMBLY
Part Number : D3391011
Drawing Number : D3391 REV.F
Project Number : N/A
Drawing Revision : F
Material :
Due Date : 30/07/2007 **Qty:** 1 **Um:** Each

Additional Product

Job Number:



Seq. #: **Machine Or Operation:** **Description :**

1.0 D6013047 SKIDTUBE MAT'L



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

SKIDTUBE MAT'L

Pick:

Qty	Part Number	Description	Batch
1	D6013-047	Extrusion	

2.0 LANDING GEAR 1 LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

Cut extrusion to 46.52 +0.010 -0.020

3.0 BENDING BENDING MACHINE



Comment: No bender

Bend as per Dwg D3391 Using Bend Prog 3391021

4.0 QC5 INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

5.0 HAAS1 HAAS CNC VERTICAL MACHINING #1



Comment: HAAS CNC VERTICAL MACHINING #1

1-Machine as per Folio FA590 Rev. ____ & Dwg D3391 Rev. ____

Identify as D3391-1

sel 2 Hacked

pg 1

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 05/11/2007 11:22:05 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD TUBE ASSEMBLY

Job Number: 33632

Part Number: D3391011

Job Number:



Seq. #:

Machine Or Operation:

Description :

2-Deburr

6.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

7.0

MILLING CONV.

CONVENTIONAL MILLING MACHINE



Comment: CONVENTIONAL MILLING MACHINE

Drill X1 Aft cap as per Dwg D3391

8.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

9.0

QC8

SECOND CHECK



Comment: SECOND CHECK

10.0

LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Drill and c'sink float bag holes as per Dwg D3391 using DT8798 (Do not open tow cap holes to finish size)
(DRILL ALL HOLES)

2-Drill Remaining two holes for tow cap using DT 8819 Locating off of .1875" holes drilled in previous step

3-Open tow cap holes to .208" as per Dwg D3391

4-Open Tow Ring hole to .640" as per Dwg D3391

5-Drill wearplate holes as per Dwg D3391 Using Dt8217

6--Deburr

11.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1







Acid etch and Alodine as per QSI 005 4.1

SL 8-1-18

P10

8-1-18

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
8-1-22	12	Magna bond <u>M166085</u> update 9-5-1 + bolts <u>B 35813</u> <u>QTY 9</u>		8-1-22	(1)		 08/01/22	
08/01/22	12	QC #5 inspect work to current step		08/01/22	(1)		 08/01/22	

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 05/11/2007 11:22:05 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD TUBE ASSEMBLY

Job Number: 33632

Part Number: D3391011

Job Number:



Seq. #:

Machine Or Operation:

Description :

12.0

POWDER COATING

POWDER COATING



M106379



(IX)

Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

M-L 08/01/25

13.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



(P)

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

FL 08/01/25

14.0

D3401041

Tow Cap Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Tow Cap Assembly

Pick:

Qty

Part Number

Description

Batch

1

D3401-041

Tow Cap

D33658

FL

15.0

D356413

WEARSHOE



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

WEARSHOE

D33867

FL

16.0

D356613

GASKET



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

GASKET

D32744

FL

17.0

AN3C4A

BOLT



Comment: Qty.: 10.0000 Each(s)/Unit Total: 10.0000 Each(s)

Bolt

Pick:

Qty

Part Number

Description

Batch

4

AN3C4A

Bolt

M106785

FL 08/01/25

18.0

NAS1515H3L

WASHER



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

Washer

Pick:

Qty

Part Number

Description

Batch

4

NAS1515H3L

Washer

M105116

FL 08/01/25

(P+10)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
08/01/25	18.1	Phenolic washers D3672-1 Qty: 4 'Batch: D34470	FL	08/01/25	4	4 08.01.20	adul30

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 05/11/2007 11:22:05 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD TUBE ASSEMBLY

Job Number: 33632

Part Number: D3391011

Job Number:



Seq. #:

Machine Or Operation:

Description :

19.0

AN960C10L

washer



Comment: Qty.: 10.0000 Each(s)/Unit Total : 10.0000 Each(s)

Washer

Pick:

Qty

Part Number

Description

Batch

4

AN960C10L

Washer

m 106552.

FL

20.0

NAS1330C3KB166

INSERT



Comment: Qty.: 30.0000 Each(s)/Unit Total : 30.0000 Each(s)

Rivnut

Pick:

Qty

Part Number

Description

Batch

24

NAS1330C3KB166

Insert

PPD

21.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Install inserts and Tow Cap as per Dwg D3391

Identify as D3391-021

FL 08/01/25

22.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

Inspect thread of each insert using DT8821

6/08/25

23.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: _____

PPD 35921

6/8/25

24.0

QC21

FINAL INSPECTION/W/O RELEASE







Comment: FINAL INSPECTION/W/O RELEASE

DD 08/01/30

Job Completion



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
08/01/25	19.1	Insert AELS-1032-130 Batch: B m105729	Fd	08/01/25	2	 08.01.25	 08.01.25	
08/01/25	19.2	Insert Insert AELS-1032-225 Batch: m100489 per Rev	Fd	08/01/25	10	 08.01.25	 08.01.25	

Part No: _____ PAR #: _____ Fault Category: U NCR: Yes ☒ No ☐ DQA: D Date: 08/01/25
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 7/19/2007 2:20:54 PM
 User: Kim Johnston

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: FWD TUBE ASSEMBLY
Job Number	: 33632		
Estimate Number	: 10467		
P.O. Number	:	Part Number	: D3391021 - 011 <i>✓</i>
This Issue	: 7/19/2007 S.O. No. :	Drawing Number	: D3391 REV.F
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: / / Type : MACHINED PARTS	Drawing Revision	: F
Previous Run	: 33631	Material	:
Written By	:	Due Date	: 7/30/2007 Qty: 1 Um: Each
Checked & Approved By	: <i>07.07.19</i>		
Comment	: Est. A 05.09.13 New issue KJ/JLM		
	: Est. B 06.02.10 Dwg rev.D ecn 773 EC		
	: Est. C 06.05.02 Added inspections EC		
	: est D 07.03.13 rev F dwg EC		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D6013047	SKIDTUBE MAT'L
-----	----------	----------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)
 SKIDTUBE MAT'L

Pick:

Qty	Part Number	Description	Batch
1	D6013-047	Extrusion	<i>B26547 DP 7-7-25</i>

2.0	LANDING GEAR 1	LANDING GEAR RESOURCE 1
-----	----------------	-------------------------



Comment: LANDING GEAR RESOURCE 1
 Cut extrusion to 46.52 +0.010 -0.020

DP 7-7-25

3.0	BENDING	BENDING MACHINE
-----	---------	-----------------



Comment: No bender
 Bend as per Dwg D3391 Using Bend Prog 3391021

EL 7-10-31

4.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



Comment: INSPECT WORK TO CURRENT STEP

E 7/11/02

5.0	HAAS1	HAAS CNC VERTICAL MACHINING #1
-----	-------	--------------------------------



Comment: HAAS CNC VERTICAL MACHINING #1
 1-Machine as per Folio FA590 Rev. *F* & Dwg D3391 Rev. *F*
 Identify as D3391-1

2-Deburr

SA 07.11.04

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD TUBE ASSEMBLY

Job Number: 33632

Part Number: D3391021

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

SA 07.11.04

7.0

MILLING CONV.

CONVENTIONAL MILLING MACHINE



Comment: CONVENTIONAL MILLING MACHINE
Drill X1 Aft cap as per Dwg D3391

Jul 02.11.04.

8.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Jul 02.11.04

9.0

QC8

SECOND CHECK



Comment: SECOND CHECK

J.L 07/11/05

10.0

LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Drill and c/sink float bag holes as per Dwg D3391 using DT8798(Do not open tow cap holes to finish size)
(ONLY DRILL HOLES MARKED "A")

2-Drill Remaining two holes for tow cap using DT 8819 Locating off of .1875" holes drilled in previous step

3-Open tow cap holes to .208" as per Dwg D3391

4-Open Tow Ring hole to .640" as per Dwg D3391

5-Deburr & Scribe Batch number Inside aft end.

11.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

12.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid etch and Alodine as per QSI 005 4.1

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 7/19/2007 2:20:55 PM

User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD TUBE ASSEMBLY

Job Number: 33632

Part Number: D3391021

Job Number:



Seq. #:

Machine Or Operation:

Description :

13.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

14.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

15.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

16.0

NAS1330C3KB166

INSERT



Comment: Qty.: 20.0000 Each(s)/Unit Total : 20.0000 Each(s)

Rivnut

Pick:

Qty	Part Number	Description	Batch
14	NAS1330C3KB166	Insert	

17.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Install Inserts as per Dwg

18.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

19.0

D3401041

Tow Cap Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Tow Cap Assembly

Pick:

Qty	Part Number	Description	Batch
1	D3401-041	Tow Cap	

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD TUBE ASSEMBLY

Job Number: 33632

Part Number: D3391021

Job Number:



Seq. #:

Machine Or Operation:

Description :

20.0

D356413

WEARSHOE



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)
WEARSHOE

21.0

D356613

GASKET



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)
GASKET

22.0

AN3C4A

BOLT



Comment: Qty.: 10.0000 Each(s)/Unit Total : 10.0000 Each(s)
Bolt
Pick:
Qty Part Number Description Batch
4 AN3C4A Bolt

23.0

NAS1515H3L

WASHER



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)
Washer
Pick:
Qty Part Number Description Batch
4 NAS1515H3L Washer

24.0

AN960C10L

washer



Comment: Qty.: 10.0000 Each(s)/Unit Total : 10.0000 Each(s)
washer

25.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: SMALL & MEDIUM FAB RESOURCE 1
Install tow Cap as per Dwg D3391
Identify as D3391-021

26.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP
Inspect thread of each insert using DT8821

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 7/19/2007 2:20:55 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD TUBE ASSEMBLY

Job Number: 33632

Part Number: D3391021

Job Number:



Seq. #:

Machine Or Operation:

Description :

27.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: _____

28.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion




W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



D3391-041/-043 FLOAT SKIDTUBE ASSEMBLY PARTS LIST

QTY -041	QTY -043	PART NUMBER	DESCRIPTION
X	X	D3391-041	FLOAT SKIDTUBE ASSEMBLY
		D3391-043	FLOAT SKIDTUBE ASSEMBLY
1		D3391-011	FWD TUBE ASSEMBLY
1		D3391-013	MID TUBE ASSEMBLY
1		D3391-015	AFT TUBE ASSEMBLY
1	1	D3391-021	FWD TUBE ASSEMBLY
1	1	D3391-023	MID TUBE ASSEMBLY
1	1	D3391-025	AFT TUBE ASSEMBLY
1	1	D3564-1	WEARSHOE
1	1	D3564-3	WEARSHOE
2	2	D3566-1	GASKET
1	1	D3566-5	GASKET
24	24	AN3C4A	BOLT
12	12	AN3C6A	BOLT
6	6	AN3C7A	BOLT
44	44	AN960C10L	WASHER
4	4	MS27039C4-12	SCREW
4	4	NAS1515H4L	WASHER
4	4	AN960C416L	WASHER

GENERAL NOTES

- 1) ALL DIMENSIONS ARE IN INCHES
- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 3) FINISH: ACID ETCH AND ALDINE PER DART QSI 005 4.1
POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3
- 4) SPRAY INSIDE OF TUBE WITH A COAT OF LPS LABORATORIES "LPS-3" AFTER FINISH AND AFTER INSTALLATION OF INSERTS. COAT ALL EXPOSED FASTENERS WITH LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY, CLEAN EXCESS OFF POWDER COATING WITH MEK DEGREASER.
- 5) USE DART DRILL TEMPLATE DT8217 TO LOCATE AND DRILL 'E' SIZE HOLES (Ø0.250-Ø0.257) FOR WEARSHOE INSERTS. C'SINK Ø0.391/Ø0.425 x 100" AS APPLICABLE AND INSTALL INSERTS EXCEPT WHERE INDICATED.

SHOP COPY
RETURN TO
ENGINEERING
CONTROLLED COPY
SUBJECT TO AMENDMENT
NOTICE

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

F	07.01.18	ADD SS WEARSHOE, GASKET REMOVE FWD SADDLE HOLE -011/-021
E	06.04.25	CHANGE TOLERANCE, EASE MANUFACTURE
D	06.01.23	UPDATE TOLERANCE, CHANGE HOLE SIZE
C	05.09.27	LENGTHEN AFT EXTENSION
B	05.06.10	DRAWING UPDATES
A	05.02.07	NEW ISSUE
DESIGN	PH	DRAWN BY
CHECKED	PH	APPROVED
DATE	07.01.18	TITLE
		412 FLOAT SKIDTUBE
		SCALE
		NTS


DART DART AEROSPACE USA, INC.
FORT WADSWORTH, WA

DRAWING NO. D3391 REV. F
SHEET 1 OF 5


RELEASED
07.03.13 AH
per ECN #974




D3391-011 ASSEMBLY AND BENDING DETAIL




D3391-021 ASSEMBLY AND BENDING DETAIL




SECTION E-E (SCALE 1:5)



SECTION D-D (SCALE 1:5)




SECTION C-C (SCALE 1:5)



VIEW Z-Z (SCALE 1:5)

D3391-011/-021 WEARSHOE ASSEMBLY




D3391-011/-021 FWD TUBE ASSEMBLY PARTS LIST


QTY - 011	QTY - 021	PART NUMBER	DESCRIPTION
X	X	D3391-011	FWD TUBE ASSEMBLY
		D3391-021	FWD TUBE ASSEMBLY
1	1	D6013-047	FWD TUBE
1	1	D3401-041	TOW CAP
1	1	D3564-13	WEARSHOE
1	1	D3566-13	GASKET
10	10	AN3C4A	BOLT
4	4	NAS1515H3L	WASHER
10	10	AN960C10L	WASHER
30	20	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)

UNCONTROLLED COPY
ENGINEERING
RETURN TO
SHOP COPY
WITHOUT NOTICE

5
DRILL "E"
(Ø0.250-Ø0.257)
C'SINK (Ø0.391 X 100')
INSTALL
NAS1330S3KB166
(12 PLACES)










SECTION B-B (SCALE 1:5)



D3391-1 DRILLING AND CUTTING DETAIL
(MAKE FROM D6013-047 SKIDTUBE MATERIAL)

COPYRIGHT © 2006 BY DART AEROSPACE USA, INC.		DESIGN PH	DRAWN BY AH	DART DART AEROSPACE USA, INC. PORT HADLOCK, MA
CHECKED JH	APPROVED JH	DRAWING NO. D3391		REV. F SHEET 2 OF 5
DATE 07.01.18		TITLE 412 FLOAT SKIDTUBE		SCALE 1:10



QTY - 013	QTY - 023	PART NUMBER	DESCRIPTION
X	X	D3391-013	MID TUBE ASSEMBLY
X	X	D3391-023	MID TUBE ASSEMBLY
1	1	D2500-1-100	EXTRUSION
1	1	D3389-1	WEB
24	20	NAS1330S3KB116	INSERT (OR NAS1330C3KB116)
24	10	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)
4	4	NAS1329S4KB140	INSERT (OR NAS1329C4KB140)
4	4	NAS1515H3L	WASHER
4	4	AN960C10L	WASHER
4	4	NAS1515H4L	WASHER
4	4	AN960C416L	WASHER
4	4	MS27039C1-09	SCREW
4	4	MS27039C4-08	SCREW


D3391-013/-023 MID TUBE ASSEMBLY
 1) MATERIAL: MAKE FROM D2500-1-100 EXTRUSION
 2) INSTALL D3389-1 WEB TO OUTER TUBE USING SHAFLEX-241/-291 PER CSI 015

WORK ORDER 33632
 SUBJECT TO AMENDMENT
 UNCONTROLLED COPY
 ENGINEERING
 SECTION X-X (SCALE 1:2)
 REMOVE 0.030 FROM TOP AND BOTTOM (0.7 FROM BOTH ENDS)


COPYRIGHT © 2006 BY DART AEROSPACE USA, INC.
 THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

DESIGN BY **PH** DRAWN BY **PH**
 CHECKED **PH** APPROVED **PH**
 DATE 07.01.18
 DRAWING NO. D3391
 TITLE 412 FLOAT SKIDTUBE
 SHEET 3 OF 5
 SCALE 1:20


RELEASED
 H 03-0513 RH
 OCT 04 0934




VIEW BB-BB
(SCALE 1:3)




D3391-3 AFT DRILLING AND CUTTING DETAIL
(MAKE FROM D6014-090 SKIDTUBE MATERIAL)




DETAIL V
(SCALE 1:2)




SECTION AA-AA
(SCALE 1:2)




SECTION N-N
(SCALE 1:2)



SECTION P-P
(SCALE 1:2)




SECTION Q-Q
(SCALE 1:2)




SECTION R-R
(SCALE 1:2)

NO. 33632
WORK ORDER
SUBJECT TO AMENDMENT
WITHOUT NOTICE
UNCONTROLLED COPY
ENGINEERING
RETURN TO
SHOP COPY



DETAIL S
(SCALE 1:3)




VIEW W-W
(SCALE 1:3)

RELEASED
07.03.13 PH
per ESN #934


COPYRIGHT © 2006 BY DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL
AND IS SUPPLIED ON THE EXPRESS CONDITION
THAT IT IS NOT TO BE USED FOR ANY PURPOSE
OR COPIED OR COMMUNICATED TO ANY OTHER
PERSON WITHOUT WRITTEN PERMISSION FROM
DART AEROSPACE USA, INC.


DESIGN PH	DRAWN BY PH	DART DART AEROSPACE USA, INC. FORT HADLOCK, MA	REV. F
CHECKED H	APPROVED H	DRAWING NO. D3391	SHEET 4 OF 5
DATE 07.01.18	TITLE 412 FLOAT SKIDTUBE	SCALE 1:12	




D3391-015 BENDING AND ASSEMBLY DETAIL



D3391-025 BENDING AND ASSEMBLY DETAIL




D3391-015 INSERT AND WEARPAD INSTALLATION DETAIL
(SEE TABLE)



D3391-025 INSERT AND WEARPAD INSTALLATION DETAIL
(SEE TABLE)


D3391-015/-025 AFT TUBE ASSEMBLY PARTS LIST

QTY - 015	QTY - 025	PART NUMBER	DESCRIPTION
X	X	D3391-015	AFT TUBE ASSEMBLY
		D3391-025	AFT TUBE ASSEMBLY
1	1	D6014-090	AFT TUBE
1	1	D2646	AFT CAP
1	1	D3537-1	WEARPAD
1	1	D3537-7	WEARPAD
1	1	D3553-1	GASKET
1	1	D3553-3	GASKET
18	14	NAS1330S3KB366	INSERT (OR AES10KB366)
4	2	NAS1330S3KB316	INSERT (OR NAS1330C3KB316)
8	6	NAS1330S3KB266	INSERT (OR NAS1330C3KB266)
4		NAS1330S3KB216	INSERT (OR NAS1330C3KB216)
16	12	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)
4		NAS1330S4KB151	INSERT (OR NAS1330C4KB151)
6	6	AN3C4A	BOLT
4	4	AN3C5A	BOLT
2	2	NAS1515H3L	WASHER
10	10	AN960C10L	WASHER




SECTION CC-CC
(SCALE 1:3)

DRILL 'Q' (#0.332-#0.338)
C'SINK (#0.529X100')
NAS1330S4KB151 INSERT (1)
(4 PLACES)



SECTION U-U
(SCALE 1:3)



DETAIL T
(SCALE 1:3)

C'SINK AND INSTALL NAS1330S3KBXXX IN HOLES MARKED CS1-CS6 AS FOLLOWS

HOLES MARKED	QTY D3391-015	QTY D3391-025	C'SINK	P/N
CS1	18	14	Ø0.425	NAS1330S3KB366
CS2	4		Ø0.391	NAS1330S3KB366
CS3	4	2	Ø0.391	NAS1330S3KB316
CS4	8	6	Ø0.391	NAS1330S3KB266
CS5	4		Ø0.391	NAS1330S3KB216
CS6	16	12	Ø0.391	NAS1330S3KB166

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

DESIGN P41	DRAWN BY B41	DART DART AEROSPACE USA, INC. PORT HADLOCK, MA
CHECKED H	APPROVED H	DRAWING NO. D3391
DATE 07.01.18	TITLE 412 FLOAT SKIDTUBE	REV. F SHEET 5 OF 5 SCALE 1:12

RELEASED
07.03.13 RH
per ECN #734

